

SECRET

OUT56895

1965 OCT 11 18 42Z

11 OCT 1965

multi

P 111831Z
 FM NPIC WASHDC
 TO RUCSC/SAC OFFUTT AFB OMAHA NEB
 RUCVAA/4030 STRAT WG OL 19 BARKSDALE AFB LA
 RUCVAA/2D RTS BARKSDALE AFB LA
 RUEKDA/DIA WASHDC
 RUECYH/NAVRECONTECHSUPPCEN SUITLAND MD
 RUEPIA/CIA WASHDC
 RUWBKN/15TH AF MARCH AFB RIVERSIDE CALIF
 RUWGAA/2AF BARKSDALE AFB LA
 BT
 S E C R E T CITE NPIC 5645.

15TH AF (FOR DI), SAC (FOR DIM/GOLDEN TREE/DOCR, DM 4) 2D AF (FOR DISC DR)

1. CAMERA B-7 WAS USED IN MISSION 8048 FLOWN ON 8 OCTOBER 1965. PROCESSING WAS ACCOMPLISHED BY BARKSDALE.

2. ORIGINAL NEGATIVE:

A. THE EXPOSURE WAS ADEQUATE AND THE RESOLUTION IS GOOD.

B. 9R SIDE: MANUFACTURING SPLICES ARE LOCATED IN FRAMES 314 AND 1731.

C. 9L SIDE: A SMALL PIECE OF THE EMULSION WAS LIFTED FROM FRAME 231 AND DEPOSITIED ON THE BACK OF FRAME 232. OTHER EMULSION LIFTS WERE DETECTED IN FRAMES 959, 1714, AND 2083. A SMALL EMULSION SCRATCH IS PRESENT IN THE CENTER OF THE FORMAT IN FRAME 411. A MANUFACTURING SPLICE IS LOCATED IN FRAME 1745 AND AN IMAGE OF THE SPLICE CAN BE DETECTED IN FRAME 1742.

D. BOTH SIDES: EDGE FOG, THE RESULTS OF STATIC DISCHARGES AND ROLLER CHATTER RECUR THROUGHOUT THE MISSION. THE 1L AND 2L FRAMES DO NOT APPEAR QUITE AS SHARP AS THE OTHER POSITIONS.

COPIES RECEIVED		
Cy No.	Office	Act.
1	File	
2	OS	
	ADMIN	
	DISC DR	
	IDS	
	CCD	
	IFD	
	PD	
	ESD	
	FC-ICB	
34	TID	
	PID	
	PEG	
	DIAGN-4	
	SPAD	
	NSA-LO	
	DIA-AP	

-2-

THE FRAME COUNTER SKIPPED FROM 0001 TO 0003. THE LAST TITLED
FRAME IS 2684.

E. THERE ARE NO MAJOR CAMERA OR PROCESSING ANOMALIES.

3. POSITIVES:

A. THE PI SUITABILITY IS GOOD.

B. THE PRINTING AND PROCESSING WAS GOOD.

C. CLOUDS OBSCURE 25 PERCENT OF THE MISSION.

GP-1

S E C R E T

-END OF MESSAGE-

1